STATUS OF FRASER SURREY DOCKS REVIEW

Based on the review to date, PMV is requiring the following additional measures:

1. Work with its rail provider to address the issue of potential dust migration from rail cars in a manner that is consistent with the best practices employed by other rail carriers into the Port;
2. Revise its proposal by employing other measures in the supply chain to remove the necessity to have a temporary stockpile on site;
3. Revise its proposal to ensure that coal dust does not migrate from the barges at the terminal and along its route to its destination;

PORT METRO vancouver